Unique Support Surface Construction Materials Influence Fluid Ingress, Longevity and Return on Investment

Neil Craney BSN, RN; Megan Hermann PT, DPT, CSPHA; Sarah Novotny PT, DPT, CWS, CLT-LANA, CFPS; Mikal Sanders PT, DPT; Stephanie Stoker BSN, RN; Kristen Thurman PT, MPT, CWS, CFPS


Surfaces requiring full replacement:

85%

0%

Surfaces from other market leading manufacturers (B, C, D)

Surfaces with unique construction from Manufacturer A



Background

Fifty percent of acute care support surfaces are compromised within 3.8 years with an increase in failure odds of 67.6% with each additional year of age. The FDA recommends regular inspection of the top cover and internal components for fluid ingress and damage and replacing damaged covers and surfaces to reduce the risk of infection to patients. 2,3,4,5

Problem

Risk for cross-contamination from compromised surfaces was shown to be 5.83 times that of controls.⁵ Replacing surfaces is costly. Preserving their integrity prevents not only infections but also unnecessary spend.

Methods


Surfaces were inspected to observe top cover and internal component damage/staining.³ A top cover with holes/tears or internal staining is recommended for replacement.³ Once the top cover was removed, internal components were inspected for damage/staining/compression and recommended for replacement if observed. Various surfaces were selected to understand how different constructions impacted surface longevity.

Interventions

A unique surface construction was assessed to understand if construction materials/methods decreased fluid ingress/cross-contamination and improved surface lifespan.

Significant Differences Between Typical and Unique Construction:

Typical Construction No Welded-Shield Layer Sewn seams Standard Top Cover Fabric Major Acute Care Support Surface Manufacturers top cover immersed in bleach for 5 days resulting in full delamination



Results

Across 24 facilities, 422 surfaces from various manufacturers with an average age of 6 years were inspected. Thirty-seven (37) surfaces (average age 5 years) contained a welded shield* to prevent fluid ingress if the top cover was damaged. None of these surfaces required full replacement and only 8% (3) required new top covers. Of the remaining 374 without a welded shield, 85% (318) sustained internal damage requiring full surface replacement.

Frequent Damage Seen With Other Leading Manufacturers



Construction: Top cover material is eroded by harsh chemical cleansers **Result:** Degraded waterproofing material allows for fluid ingress



Construction: Sewn seams create thousands of holes in cover **Result:** Holes allow fluid to permeate the interior components



Construction: Fiberglass fire barrier breaks down over time and is chemically treated. **Result:** No longer offers fire protection



Construction: Unprotected interior components Result: Fluid ingress and contamination of interior components, requires full replacement of the surface for patient safety.

Damage Prevented with Unique Support Surface Construction



formulated top cover fabric Result: No delamination of waterproofing, maintains integrity, and no fluid ingress

Construction: Specially



Construction: RF-welded seams permanently bond the material on a molecular level **Result:** Avoiding holes to join fabric prevents fluid intrusion



Construction: Fiberglass-free fire barrier Result: Remains intact over time ensuring adequate fire protection.



Construction: Welded shield protected interior components

Result: The welded shield prevents fluid ingress to interior components if top cover would get damaged, further preventing full replacement

Implications for Practice

Unique materials and construction prevented fluid ingress and contamination of surfaces preserving longevity of costly assets. Previous studies have shown that most surfaces sustain internal damage triggering replacement in less than five years. None of the surfaces in this study with a welded shield required full replacement—only three top covers (~\$1,300 less than cost of a new surface). Taking this analysis further, the cost of replacing 318 surfaces would be ~\$477,000—where replacing 8% of top covers only would be ~\$6,000. Surfaces with a welded-shield construction yield significant cost savings. Considering at 5 years the surfaces with welded shields did not require replacement, inspection of these surfaces beyond 5 years is warranted to understand total useful life.

Additional Spend Required for Patient Safety In a 400 Bed Hospital by Year 5

Manufacturer	Surfaces Requiring Replacement	Cost
Α	0%	\$0
В	68%	\$408,000
С	78%	\$468,000
D	88%	\$528,000

*Assuming \$1,500 surface replacement cost

REFERENCES

- 1. Koshy T, Manista G, Nicholson L, Ikpeze T, Todd J, Black J. The state of support surface integrity in acute healthcare facilities. Poster presented at: NPIAP 2023 Annual Conference. March 17-19, 2023. San Diego, CA.
- 2. "Safety Communications Damaged or Worn Covers for Medical Bed Mattresses Pose Risk of Contamination and Patient Infection: FDA Safety Communication." FDA Archive, Center for Devices and Radiological Health, wayback.archive-it.org/7993/20161022044101/http://www.fda.gov/MedicalDevices/Safety/AlertsandNotices/ucm348016.htm. Accessed 5 Sept. 2023.
- 3. Center for Devices and Radiological Health. Covers for hospital bed mattresses keep them safe. U.S. Food and Drug Administration. Accessed September 27, 2023. https://www.fda.gov/medical-devices/hospital-beds/covers-hospital-bed-mattresses-learn-how-keep-them-safe#:-:text=Over%20time%2C%20hospital%20bed%20mattress%20covers%20can%20wear,out%20the%20next%20time%20 the%20mattress%20is%20used.
- 4. Creamer E, Humphreys H. Journal of Hospital Infection. The contribution of beds to healthcare-associated infection: the importance of adequate decontamination. 2008;69:8-23. doi:doi:10.1016/j.jhin.2008.01.014
- 5. Sivek A, Davis J. How Wet Is Your Patient's Bed? Blood, Urine, and Microbiological Contamination of Mattresses and Mattress Covers. Patient Safety Advisory. 2018;15(4). http://patientsafety.pa.gov/ADVISORIES/Pages/201812_FluidIngress.aspx. Accessed September 27, 2023.

A= Agiliti® B-D = Other market leading surface manufacturers *Core Shield™ by Agiliti®

