### BACKGROUND

Fifty percent of acute care support surfaces are compromised within 3.8 years with an increase in failure odds of 67.6% with each additional year of age.<sup>1</sup> The FDA recommends regular inspection of the top cover and internal components for fluid ingress and damage and replacing damaged covers and surfaces to reduce the risk of infection to patients.<sup>2,3,4,5</sup>

#### PROBLEM

Risk for cross-contamination from compromised surfaces was shown to be 5.83 times that of controls.<sup>5</sup> Replacing surfaces is costly. Preserving their integrity prevents not only infections but also unnecessary spend.

#### METHODS

Surfaces were inspected to observe top cover and internal component damage/staining.<sup>3</sup> A top cover with holes/tears or internal staining is recommended for replacement.<sup>3</sup> Once the top cover was removed, internal components were inspected for damage/staining/compression and recommended for replacement if observed. Various surfaces were selected to understand how different constructions impacted surface longevity.

#### INTERVENTIONS

A unique surface construction was assessed to understand if construction materials/methods decreased fluid ingress/cross-contamination and improved surface lifespan.

#### Significant differences between typical and unique construction:





No Welded-Shield Layer



Sewn seams



Standard Top Cover Fabric

Maior Acute Care Support Surface Manufacturers top cover immersed in bleach for 5 days resulting in full delamination

# **Unique Support Surface Construction Materials Influence** Fluid Ingress, Longevity and Return on Investment

Neil Craney BSN, RN; Megan Hermann PT, DPT, CSPHA; Sarah Novotny PT, DPT, CWS, CLT-LANA, CFPS; Mikal Sanders PT, DPT; Stephanie Stoker BSN, RN; Kristen Thurman PT, MPT, CWS, CFPS

#### **Percentage of Replacements Required**



# **Frequent Damage Seen With Other Leading Manufacturers**



is eroded by harsh chemical **Result:** Degraded waterproofing material allows for fluid ingress



**Construction:** Sewn seams create permeate the interior components



**Construction:** Fiberglass fire and is chemically treated. **Result:** No longer offers fire

### **Damage Prevented with Unique Support Surface Construction**



**Construction:** Specially waterproofing, maintains integrity, and no fluid ingress



**Construction:** RF-welded seams permanently bond the material on **Result:** Avoiding holes to join fabric prevents fluid intrusion



**Construction:** Fiberglass-free fire **Result:** Remains intact over time ensuring adequate fire protection.



Specially Formulated Top Cover Fabric (4-Way Stretch, Breathable, Waterproof) Manufacturer A's top cover immersed in bleach for 10 days resulting in no delamination

# **Surfaces requiring** full replacement:

85%

Surfaces from other market leading manufacturers (B, C, D)

Surfaces with unique construction from Manufacturer A







Construction: Unprotected interior components

Result: Fluid ingress and contamination of interior components, requires full replacement of the surface for patient safety.



**Construction:** Welded shield protected interior components

**Result:** The welded shield prevents fluid ingress to interior components if top cover would get damaged, further preventing full replacement

# RESULTS

Across 24 facilities, 422 surfaces from various manufacturers with an average age of 6 years were inspected. Thirty-seven (37) surfaces (average age 5 years) contained a welded shield\* to prevent fluid ingress if the top cover was damaged. None of these surfaces required full replacement and only 8% (3) required new top covers. Of the remaining 374 without a welded shield, 85% (318) sustained internal damage requiring full surface replacement.

## IMPLICATIONS FOR PRACTICE

Unique materials and construction prevented fluid ingress and contamination of surfaces preserving longevity of costly assets. Previous studies have shown that most surfaces sustain internal damage triggering replacement in less than five years. None of the surfaces in this study with a welded shield required full replacement—only three top covers (~\$1,300 less than cost of a new surface). Taking this analysis further, the cost of replacing 318 surfaces would be ~\$477,000—where replacing 8% of top covers only would be ~\$6,000. Surfaces with a welded-shield construction yield significant cost savings. Considering at 5 years the surfaces with welded shields did not require replacement, inspection of these surfaces beyond 5 years is warranted to understand total useful life.

#### Additional Spend Required for Patient Safety In a 400 Bed Hospital by Year 5

Manufacturer	Surfaces Requiring Replacement	Cost
А	<b>0%</b> (0)	\$O
В	<b>68%</b> (272)	\$408,000
С	<b>78%</b> (312)	\$468,000
D	<b>88%</b> (352)	\$528,000

\*Assuming \$1,500 surface replacement cost

#### REFERENCES

- 1. Koshy T, Manista G, Nicholson L, Ikpeze T, Todd J, Black J. The state of support surface integrity in acute healthcare facilities. Poster presented at: NPIAP 2023 Annual Conference. March 17-19, 2023. San Diego, CA.
- 2. "Safety Communications Damaged or Worn Covers for Medical Bed Mattresses Pose Risk of Contamination and Patient Infection: FDA Safety Communication." FDA Archive, Center for Devices and Radiological Health, wayback.archive-it.org/7993/20161022044101/ http://www.fda.gov/MedicalDevices/Safety/AlertsandNotices/ ucm348016 htm. Accessed 5 Sept. 2023
- 3. Center for Devices and Radiological Health. Covers for hospital bed mattresses - keep them safe. U.S. Food and Drug Administration. Accessed September 27, 2023. https://www.fda.gov/medical-devices/ hospital-beds/covers-hospital-bed-mattresses-learn-how-keep-themsafe#:~:text=Over%20time%2C%20hospital%20bed%20mattress%20 covers%20can%20wear,out%20the%20next%20time%20the%20 mattress%20is%20used.
- 4. Creamer E, Humphreys H. Journal of Hospital Infection. The contribution of beds to healthcare-associated infection: the importance of adequate decontamination. 2008:69:8-23. doi:doi:10.1016/j.jhin.2008.01.014
- Sivek A. Davis J. How Wet Is Your Patient's Bed? Blood, Urine and Microbiological Contamination of Mattresses and Mattress Covers. Patient Safety Advisory. 2018;15(4). http://patientsafety. pa.gov/ADVISORIES/Pages/201812\_FluidIngress.aspx. Accessed September 27, 2023.





A= Agiliti and Core Chield line. B-D = Other market leading surface manufacturers \*Core Shield™ by Agiliti®

CLI-0061F-0324